

Sent via email

July 20, 2023

TV Tracking #: 746 (B2626) TV Tracking #: 747 (A0901) TV Tracking #: 748 (B5574)

Refinery, Asphalt Plant & B5574 June 2023 30-Day Title V Deviation Reports Monitoring Reports for January 2023-June 2023

1. D RECEIVED IN 07/21/2023 ENFORCEMENT:

> Mr. Jeff Gove Director of Compliance and Enforcement Bay Area Air Quality Management District 375 Beale Street, Suite 600 San Francisco, CA 94105

Dear Mr. Gove:

Per Standard Condition I.F of Valero's Title V permits issued for the Fuels Refinery (B2626) and the Asphalt Plant (A0901) and Permit B5574, enclosed are 30-day deviation reports summarizing June 2023 Title V deviations for all three permits. Also enclosed are the certified Semi-Annual Monitoring Title V reports for all three facilities. Please note that the reporting convention for these reports is that deviations *discovered* during the calendar month are included along with any on-going events, regardless of when the event started.

The format and content of these reports is consistent with guidance provided by Mr. Steve Hill, BAAQMD Permit Evaluation Manager, in his letter dated January 8, 2004.

Please contact me at 707-745-7637 if you have any questions or need further information.

Sincerely,

ina lit

Rina Putnam Staff Environmental Engineer

Ecc : Marie Miller, <u>mmiller@baaqmd.gov</u> <u>compliance@baaqmd.gov</u>

Enclosures

From 6/1/2023 to 6/30/2023

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Event Starte	1:05 PM Ongoing Event
	May have resulted in a violation of:
Source Number: S1010-Hydrogen Production Facilities	Permit: 27609 Part 1
Abatement Device:	AQMD: Reg 8-2-301
Emission Point: P1010-ST-302	Other:
	<u>0 pm - 1:05 pm and approximately 119 lbs of total carbon was released from vent P1010 (ST-302) to</u> ay to address releases from this vent during startup, shutdown and process upsets.

Probable Cause: <u>1900# hydrogen grid experienced grid instability due to change in hydrogen demand by hydrogen consumer.</u>

Corrective actions or <u>Hydrogen Grid pressure was stablilized.</u>

preventative steps taken:

Episode ID #: 08S97

NOV:

From 6/1/2023 to 6/30/2023

B2626 Valero Benicia R	efinery				
Facility Address:			Mailing Address:		
3400 East Second Street			3400 East Second Stre	et	
Benicia, CA 945101097			Benicia, CA 94510109	7	
Contact: Taryn Wier		Title: Manager ·	Environmental Engineering	Phone: (707)	745-7475
ertification Statement		ų.			
ertify under penalty of law that based on the asonable inquiry, the statements and inform tachments and other materials are true, acc	ation in this document	t and in all	Vice President and General M	Лаnager	7/20/23
ignature of Responsible Official	Print Name		Title		Date

116

From 6/1/2023 to 6/30/2023

901 Valero Benicia Asphalt	Plant	
Facility Address:	Mailing Address:	
3001 Park Road	3001 Park Road	
Benicia, CA 94510	Benicia, CA 94510	
Contact: Taryn Wier	Title: Manager - Environmental Engineering	Phone: (707) 745-7475

No deviation for this time period.

Certification Statement

I certify under penalty of law that based on the information and belief formed after reasonable inquiry, the statements and information in this document and in all attachments and other materials are true, accurate, and complete.

х Signature of Responsible Official

Joshua Tulino

Vice President and General Manager

23 Date

Tuesday, July 18, 2023

Print Name

Title

From 6/1/2023 to 6/30/2023

74 Nustar Logistics	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 94510	Benicia, CA 945101097
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475

No deviation for this time period.

Certification Statement

I certify under penalty of law that based on the information and belief formed after reasonable inquiry, the statements and information in this document and in all attachments and other materials are true, accurate, and complete.

х

Joshua Tulino

Vice President and General Manager

7/20/23 Date

Signature of Responsible Official

Print Name

The Fresherit and General W

Title

Tuesday, July 18, 2023

B2626 Valero Benicia Refinery			
Facility Address:	Mailing Address:		
3400 East Second Street Benicia, CA 945101097	3400 East Second Street Benicia, CA 945101097		
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475		
Title V deviations for the reporting period are summarized below:			
Event Start: <u>3/15/2023</u> 7:55 AM Stoppec <u>3/15/2023</u>	7:55 AM Ongoing Event May have resulted in a violation of:		
Source Number: Abatement Device: Emission Point:	Permit:		
	y received an NOV (62179) from the BAAQMD. The NOV was issued for exceeding the 3-hr 162 ppm on December 10, 2021. Valero does not agree with this NOV and submitted a response letter on		
	y received an NOV (62179) from the BAAQMD. The NOV was issued for exceeding the 3-hr 162 ppm on December 10, 2021. Valero does not agree with this NOV and submitted a response letter on		
	y received an NOV (62179) from the BAAQMD. The NOV was issued for exceeding the 3-hr 162 ppm on December 10, 2021. Valero does not agree with this NOV and submitted a response letter on		
Episode ID #:	NOV: <u>62179</u>		

B2626 Valero	Benicia Refinery	
Facility Address:	Mai	ailing Address:
3400 East Second S Benicia, CA 945102		3400 East Second Street Benicia, CA 945101097
Contact: Taryn W	Vier Title: Manager - Environme	nental Engineering Phone: (707) 745-7475
Title V deviations for the reportin	ng period are summarized below:	
Event Starte	7:55 AM Stoppec <u>3/15/2023</u> 7:55 AM Ongoing Event	
		May have resulted in a violation of:
Source Number:		Permit:
Abatement Device:		AQMD:
Emission Point:		Other: 40 CFR 63.670
1243 Event Description: On N	Narch 15, 2023, Valero Benicia Refinery received NOV (62178) from	n the BAAQMD. The NOV was issued for exceeding the limit of no visible
<u>emiss</u>	sions for greater than 5 minutes in any 2 consecutive hour period fro	from the North and South Flare on July 21, 2022.
Probable Cause: <u>On M</u>	larch 15, 2023, Valero Benicia Refinery received NOV (62178) from t	n the BAAQMD. The NOV was issued for exceeding the limit of no visible
emiss	sions for greater than 5 minutes in any 2 consecutive hour period fro	from the North and South Flare on July 21, 2022.
Corrective actions or On M	larch 15, 2023, Valero Benicia Refinery received NOV (62178) from t	n the BAAQMD. The NOV was issued for exceeding the limit of no visible
preventative steps taken: emiss	sions for greater than 5 minutes in any 2 consecutive hour period fro	from the North and South Flare on July 21, 2022.
Episode ID #:		NOV: <u>62178</u>

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below	w:
Event Start: <u>3/23/2023 11:00 AM</u> Stoppec <u>3/23/20</u>	023 11:00 AM Ongoing Event May have resulted in a violation of:
Source Number: S1006-Crude Distillation (Pipestill)	Permit:
Abatement Device:	AQMD: 8-18 -307
Emission Point:	Other:
1244 Event Description: Sample point and sample waste cor	tainer not closed and visually leaking more than 3 drips per minute.
Probable Cause: Sampling point and waste contained	r not closed after use.
Corrective actions or <u>Closed sample point and closed sam</u> preventative steps taken:	nple waste container.
Episode ID #:	NOV: <u>62180</u>

B2626	Valero Benicia Refinery			
Facility Addro	ess:	Maili	ing Addre	ss:
3400 East	Second Street	34	400 East S	Second Street
Benicia, C	A 945101097	B	enicia, CA	945101097
Contact	: Taryn Wier	Title: Manager - Environme	ntal Engir	neering Phone: (707) 745-7475
Title V deviations for th	ne reporting period are summarized below:			
Event Starte3/31,	/2023 9:30 AM Stopper <u>3/31/2023</u>	9:50 AM 🗌 Ongoing Event		May have resulted in a violation of:
Source Number: S	81-Tank TK-1753		Permit:	
Abatement Device:				8-5-322.5
Emission Point:			Other:	
1246 Event Descripti	ion: During a tank seal inspection on TK-175	3 contract inspector identified a g	<u>ap greater</u>	than regulation 8-5 criteria.
Probable Cau	use: Normal wear.			
Corrective actions preventative steps tak	or <u>Equipment maintenance; gaps were clo</u> sen:	osed and rechecked.		
Episode II	D #:		NOV:	<u>62183</u>

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start: <u>3/30/2023</u> 9:30 AM Stopper <u>3/30/2023</u>	9:52 AM Ongoing Event
	May have resulted in a violation of:
Source Number: S220-Hot Oil Furnace, F-4460	Permit:
Abatement Device:	AQMD: 8-18-301
Emission Point:	Other:
	ppm total organic compounds during BAAQMD inspection on 3/30/23. The leaking equipment was April 5, 2023, Valero Benicia Refinery received NOV (62181) from the BAAQMD. The NOV was issued for 100 ppm from flexible fuel line.
Probable Cause: Normal wear	
Corrective actions or <u>Lines were blocked in and isolated and re</u> preventative steps taken:	paired.
Episode ID #:	NOV: <u>62181</u>

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Wier Title: Ma	nager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start: <u>4/3/2023 1:48 PM</u> Stoppec <u>4/3/2023 2:05 PM</u>	Ongoing Event May have resulted in a violation of:
Source Number: S220-Hot Oil Furnace, F-4460	Permit:
Abatement Device:	AQMD: 8-18.301
Emission Point:	Other:
	rganic compounds during BAAQMD inspection on 4/3/23. The leaking equipment was 3, Valero Benicia Refinery received NOV (62182) from the BAAQMD. The NOV was issued for 5 com flexible fuel line.
Probable Cause: Normal wear	
Corrective actions or <u>Lines have been blocked in and isolated and repaired</u> preventative steps taken:	<u>.</u>
Episode ID #:	NOV: <u>62182</u>

From 1/1/2023 to 6/30/2023

B2626 Valero Benicia Refiner	ſ¥			
Facility Address:	Maili	ng Addre	ess:	
3400 East Second Street	34	400 East S	Second Stree	t
Benicia, CA 945101097	Be	enicia, CA	945101097	,
Contact: Taryn Wier	Title: Manager - Environme	ntal Engir	neering	Phone: (707) 745-7475
Title V deviations for the reporting period are summar	ized below:			
Event Start: <u>12/14/2015 12:00 AM</u> Stoppec	Ongoing Event			
]	May have res	sulted in a violation of:
Source Number: S1010-Hydrogen Production Faci	lities	Permit:		
Abatement Device:			8-2-301	
Emission Point: P1010-ST-302		Other:		
1073 Event Description: <u>The BAAQMD determined</u> <u>the Catalytic Reformer (NR</u>		rom the h	<u>ydrogen vent</u>	(H2P017). These emissions are attributed to
Probable Cause: Hydrogen plant configurati	on			
Corrective actions or <u>Amendment 7/20/23: SOA</u> preventative steps taken: <u>engineering since May 202</u>			onthly status r	eports being submitted to BAAQMD
Ongoing; remedies being ir	ivestigated			

Episode ID #:

NOV: <u>58465; 59514</u>

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized	below:
Event Start(<u>6/1/2007 12:00 PM</u> Stoppec	✓ Ongoing Event May have resulted in a violation of:
Source Number: S1010-Hydrogen Production Facilitie	Permit:
Abatement Device:	AQMD: 8-28
Emission Point:	Other:
been compiled in 2007. This d data from vents, as well as rele atmospheric PRDs for a total o Discovered 19 Atmospheric Pre	ssue Relief Devices (PRDs), in the hydrogen unit, missing from the Reg 8-28 list which had been compiled in ut while preparing the response to the Reg 13-5 Information Request which requested release data from vents, as
	lizing the extent of non-methane hydrocarbons in the H2 streams.
Corrective actions or <u>Amendment 7/20/23: Permit</u> preventative steps taken:	xemption package submitted to BAAQMD on 7/18/23. Project will route all 19 PRDs to flare.
Episode ID #:	NOV: 59513; 59526; 59609; 60806; 60805; 62188
	110 V. <u>33313, 33320, 33003, 00800, 00803, 02188</u>

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Wier Title: Manager -	Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start(<u>1/15/2023 11:00 PM</u> Stoppec <u>1/16/2023 2:00 AM</u> Ongo	Ding Event
	May have resulted in a violation of:
Source Number: S1030-Combustion Turbine Generator, GT-4901; S1031-Heat Recov Generator, SG-4901	rery Steam Permit: PC #19177.19(b);PC #19177.19(a)
Abatement Device:	AQMD:
Emission Point: P60-Cogen Stack GT/SG-4901	Other:
1226 Event Description: <u>GT-4901/SG-4901 exceeded the 7.29lb/hr NOx limit on 1/15/</u> 02:00 on 11/16/22. The average concentration during the ex-	
Probable Cause: Seal Leak on P-4901 caused all NOx water from to GT4901 to	stop for 15 minutes.
Corrective actions or <u>A spare pump was started to reintroduce NOx water flow.</u> preventative steps taken:	
Episode ID #: <u>08Q21;08Q21</u>	NOV:

From	1/1	/2023	to 6	/30	/2023
------	-----	-------	------	-----	-------

B2626 Va	alero Benicia Refinery					
Facility Address	Facility Address: Mailing Address:					
3400 East Se	econd Street	3400 East	Second Street			
Benicia, CA	945101097	Benicia, C	A 945101097			
Contact: T	Taryn Wier Title: Manager - Environm	Title: Manager - Environmental Engineering Phone: (707) 745-7475				
Title V deviations for the r	reporting period are summarized below:					
Event Starte1/12/20	023 12:03 PM Stopper 7/13/2023 10:48 AM Congoing Event					
			May have resulted in a violation of:			
	ssigned-Tank, Refrigerated Butane Tank, TK-1726	Permit:				
Abatement Device:			8-5-306.2			
Emission Point:		Other:				
1227 Event Description: Ammendment 7/19/23: Valve replacement efforts are complete.						
Probable Cause	Four PV Vents on TK1726 exceeded 500ppm emission standard during E PV Vents not gas tight	AAQMD ins	spection on 1/12/23. Valve replacement efforts in progress.			
	Contacted Valero Maintenance to obtain spare PV Vents and to schedul	e crew and	crane to replace PV Vents. IDAR Tags - #178148 (SV1734B)			
preventative steps taken: #178146 (SV17110) #181671 (SV17111) #178142 (SV17109)						
	Recheck Dates - (SV1734B 7/13/23) (SV17110 6/21/23) (SV17111 6/	14/23) (S	<u>V17109 6/7/23)</u>			
	Update on 4/18/23 for LDAR Tag #178142, SV-17109 was replaced w	ith SV-1716	OSP and has passed at 89 ppm.			
Episode ID #	t:	NOV:	<u>60589; 60591</u>			

From 1/1/2023 to	6/30/2023
------------------	-----------

B2626 Valero Benicia Refinery	
Facility Address: Maili	ing Address:
3400 East Second Street 34	400 East Second Street
Benicia, CA 945101097 Be	enicia, CA 945101097
Contact: Taryn Wier Title: Manager - Environme	ental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	_
Event Starte <u>1/18/2023 11:39 AM</u> Stopper <u>1/18/2023 11:39 AM</u> Ongoing Event	
	May have resulted in a violation of:
Source Number:	Permit:
Abatement Device:	AQMD: 1-523.3; 2-1-307
Emission Point: P3-North Flare Emission Point, P-3; P2-South Flare Emission Point, P-2	Other:
1228 Event Description: <u>On January 18, 2023, Valero Benicia Refinery received 20 NOVs (60578,60</u> 60583,60584,60585,60586,60587,60818,60819,60820,60821,60822,6082 issued for operating below 270 BTU/SCF & late reported parametric. Vale	3,60824,60825,60826,60827) from the BAAQMD. The NOVs were
Probable Cause: On January 18, 2023, Valero Benicia Refinery received 20 NOVs (60578,60	
60583,60584,60585,60586,60587,60818,60819,60820,60821,60822,6082	
issued for operating below 270 BTU/SCF & late reported parametric. Vale	
Corrective actions or <u>On January 18, 2023, Valero Benicia Refinery received 20 NOVs (60578,60</u> preventative steps taken: 60583,60584,60585,60586,60587,60818,60819,60820,60821,60822,6082	
issued for operating below 270 BTU/SCF & late reported parametric. Vale	
Episode ID #:	NOV: <u>60578; 60579; 60580; 60581; 60582; 60583; 60584; 60585;</u> <u>60586; 60587; 60818; 60819; 60820; 60821; 60822; 60823;</u> <u>60824; 60825; 60826; 60827</u>

B2626 Valero Benicia Refinery					
Facility Address:	Mailing Address:				
3400 East Second Street	3400 East Second Street				
Benicia, CA 945101097	Benicia, CA 945101097				
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475				
Title V deviations for the reporting period are summarized below:					
Event Start: <u>1/28/2023 12:00 AM</u> Stoppec <u>1/28/2023</u>	4:42 AM Ongoing Event				
	May have resulted in a violation of:				
Source Number: S1010-Hydrogen Production Facilities; S1004-C (Powerformer)	atalytic Reformer Permit: 27609 Part 1				
Abatement Device:	AQMD: Reg. 8-2-301				
Emission Point: P1010-ST-302	Other:				
1229 Event Description: On 1/28/23, during a planned shutdown of a downstream Hydrogen consuming unit, P017 valve opened intermittently from 12:05 am - 4:41 am and approximately 56 lbs of total carbon was released from vent P1010 (ST-302) to atmosphere. A project has been underway to address releases from this vent during startup, shutdown and process upsets.					
Probable Cause: <u>1900# hydrogen grid experienced grid in</u>	stability while shutting down HCU and ramping down production from the H2 trains.				
Corrective actions or <u>H2 production was ramped down and hy</u> preventative steps taken:	drogen grid pressure was stabilized.				
Episode ID #: <u>08Q47</u>	NOV: <u>62193</u>				

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Wier Title: Manage	er - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Starte <u>6/26/2013</u> Stoppec <u>6/26/2013</u> 0	ngoing Event
Course Number C4040 Under see Draduction Excitition	May have resulted in a violation of:
Source Number: S1010-Hydrogen Production Facilities	Permit:
Abatement Device:	AQMD: 8-2-301
Emission Point:	Other: 40 CFR 63.643
	NOV (60588) from the BAAQMD. The NOV was issued for exceeding the 15 lb/day and s 3A and 3B at the H2U on 6/26/13. Valero submitted a response letter by 2/3/23.
Probable Cause: On January 26, 2023, Valero Benicia Refinery received an I	NOV (60588) from the BAAQMD. The NOV was issued for exceeding the 15 lb/day and
300 ppm total carbon limits from Vents 2A & 2B and Vents	s 3A and 3B at the H2U on 6/26/13. Valero submitted a response letter by 2/3/23.
Corrective actions or On January 26, 2023, Valero Benicia Refinery received an I	NOV (60588) from the BAAQMD. The NOV was issued for exceeding the 15 lb/day and
preventative steps taken: 300 ppm total carbon limits from Vents 2A & 2B and Vents	s 3A and 3B at the H2U on 6/26/13. Valero submitted a response letter by 2/3/23.
Episode ID #:	NOV: <u>60588</u>

B2626 Valero Benicia Refi	nery			
Facility Address:	Maili	ng Addre	ress:	
3400 East Second Street	34	3400 East Second Street		
Benicia, CA 945101097	Ве	enicia, CA	CA 945101097	
Contact: Taryn Wier	Title: Manager - Environme	ntal Engir	gineering Phone: (707) 745-7475	
Title V deviations for the reporting period are sum	marized below:			
Event Start: <u>1/30/2023 12:00 PM</u> Stopp	ec <u>1/30/2023 4:00 PM</u> Ongoing Event		May have resulted in a violation of:	
Source Number: S37-Waste Heat Boiler, SG-70)2	1		
Abatement Device:		AQMD:	D:	
Emission Point:		Other:	r:	
-	nce of the three hour rolling NOx concentration lim ed excess was 10.4 ppm.	iit from 1:0	1:00 pm to 4:00 pm. The average concentration for the	
Probable Cause: Analyzer saturation iss	ue			
Corrective actions or <u>Confirmation of stable</u> preventative steps taken:	operation of fuel combustion and steam production	n; replacei	cement of CEMS ammonia filter.	
Episode ID #: <u>08Q48</u>		NOV:	V:	

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start(<u>1/1/2023 12:00 AM</u> Stoppec <u>1/1/2023</u>	12:00 AM Ongoing Event
	May have resulted in a violation of:
Source Number: S5-FCCU Regenerator, R-702	Permit: 24245.14, Standard Condition F
Abatement Device: A1047-Flue Gas Scrubber (Belco & Cansolv)	AQMD:
Emission Point: P1059-FGS Stack ST-5601	Other: §60.105(a)(12)(ii)
1232 Event Description: <u>A Cylinder Gas Audit was not performed</u> of the quarter.	for the Flue Gas Scrubber CEMS in Q4 of 2022. This incident was not reported within 10 days of the end
Probable Cause: <u>I&E and Environmental did not have an i</u>	independent verification system to confirm if a CGA was needed and scheduled.
Corrective actions or <u>A CGA was completed on 2/2/23. An inc</u> preventative steps taken: <u>check the schedule to verify planning an</u>	dependent verification system for analyzers that require quarterly audits is being developed that will Id completion of CGAs each quarter.
Episode ID #:	NOV: <u>60590</u>

B2626 Va	alero Benicia Refinery			
Facility Address	:	Mailir	ng Addres	SS:
3400 East Se Benicia, CA		3400 East Second Street Benicia, CA 945101097		
Contact: T	aryn Wier T	Fitle: Manager - Environmen	ntal Engin	eering Phone: (707) 745-7475
Title V deviations for the r	eporting period are summarized below:			
Event Starte2/2/20	23 2:00 AM Stopper 2/17/2023 5	5:00 AM Ongoing Event		May have resulted in a violation of:
Source Number: S21-I	Hydrogen Reformer Furnace, F-301		Г	10574 Part 31
Abatement Device:	P31-F-301 West/East Stack, P-30/P-31		AQMD: Other:	
1234 Event Description:	on 2/17/2023. The average concentration du AMENDMENT: The F-301 rolling 24-hour No 2/17/2023.	uring the excess was 79 ppm. ox limit of 60 ppm was exceede	ed at 02:00	at 02:00 on 2/2/2023 and returned to compliance at 05:00
	The F-301 rolling 24-hour Nox limit of 60 ppr	m was exceeded at 02:00 on 2/	<u>/2/2023 ar</u>	nd is ongoing.
	Curtailed operations			
Corrective actions or preventative steps taken:	Unit was returned to normal operation.			
Episode ID #:			NOV:	

B2626 Valero Benicia Refinery		
Facility Address:	Mailir	ng Address:
3400 East Second Street		100 East Second Street
Benicia, CA 945101097	Ве	enicia, CA 945101097
Contact: Taryn Wier	Title: Manager - Environmen	ntal Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:		
Event Starte <u>4/20/2023 9:00 AM</u> Stopper <u>4/20/2023</u>	3:00 PM Ongoing Event	
		May have resulted in a violation of:
Source Number: S1031-Heat Recovery Steam Generator, SG-490 Generator, GT-4901	1; S1030-Combustion Turbine	Permit: 19177.19b, 19177.19a
Abatement Device:		AQMD:
Emission Point:		Other:
	-	following indicated excess is being filed in an abudance of caution. The The NOX 3hr average (lb/hr) limit was exceeded between 09:00 -
Probable Cause: NOx Analyzer Communication Issue.		
Corrective actions or <u>NOx Analyzer wire ribbons were adjustec</u> preventative steps taken:	<u>1.</u>	
Episode ID #: <u>08S43;08S43</u>		NOV:

B2626	Valero Benicia Refinery				
Facility Add	ress:	Maili	ng Addre	ss:	
3400 Eas	t Second Street	3400 East Second Street			eet
Benicia, C	CA 945101097	Be	enicia, CA	94510109	97
Contac	t: Taryn Wier	Title: Manager - Environme	ntal Engir	neering	Phone: (707) 745-7475
Title V deviations for t	he reporting period are summarized below:				
Event Starte 2/14	1/2023 12:00 AM Stoppec 2/14/2023	1:47 PM Ongoing Event		May have r	esulted in a violation of:
Source Number: S	8-Coke Silos Primary Scrubber, CYC-1901		1		21233, Part 7
Abatement Device:	· · · ·			9-10-502.1	
Emission Point:			Other:		
1238 Event Descript	tion: Source test report for S-8 was turned in 6 within 60 days of the source test.	51 days after the source test was	performed	1. Regulatior	n 9-10-502.1 requires source tests to be turned in
Probable Ca	use: Employee missed the due date.				
Corrective action preventative steps ta	s or <u>Source test report was submitted.</u> ken:				
Episode	ID #:		NOV:		

B2626	Valero Benicia Refinery							
Facility Addre	255:	Mailir	ng Addre	255:				
	Second Street A 945101097		3400 East Second Street Benicia, CA 945101097					
Contact:	Taryn Wier	Title: Manager - Environmer	ntal Engir	neering Phone: (707) 745-7475				
Title V deviations for the	e reporting period are summarized below:							
Event Starte2/17/2	2023 9:49 PM Stoppec _ 2/17/2023	10:33 PM Ongoing Event						
				May have resulted in a violation of:				
	010-Hydrogen Production Facilities; S1004-Ca owerformer)	atalytic Reformer	Permit:	27609 Part 1				
Abatement Device:			AQMD:	Reg. 8-2-301				
Emission Point: P1	.010-ST-302		Other:					
1239 Event Descriptic	-			kimately 305 lbs of total carbon was released from vent P1010 s vent during startup, shutdown and process upsets.				
Probable Caus	se: 1900# hydrogen grid experienced grid ins	tability while lining up H2UA train	n to produ	uction header in preparation for HCU startup.				
Corrective actions of preventative steps take	or <u>Moves were made quickly to utilize #4 ve</u> en:	nts and cut rates as needed to sta	abilize Hyd	drogen grid pressure.				
Episode ID) #: <u>E-08Q93</u>		NOV:	<u>62194</u>				

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Wier Title: Manager - Envir	onmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start(<u>2/23/2023 3:19 PM</u> Stoppe(<u>2/23/2023 3:19 PM</u> Ongoing Ev	ent
	May have resulted in a violation of:
Source Number:Abatement Device:	AQMD:
Emission Point: P3-North Flare Emission Point, P-3; P2-South Flare Emission Point, P-2	Other: 40 CFR 60.103a(h)
1240 Event Description: <u>AMENDMENT 3/27/23</u> : <u>On February 23, 2023, Valero Benicia Refir</u> <u>exceeding the 3-hr 162 ppm H2S limit from the North and South Fl.</u> <u>3rd,2023.</u>	ery received an NOV (60592) from the BAAQMD. The NOV was issued for are on August 21, 2020. Valero submitted a response letter on March
	592) from the BAAQMD. The NOV was issued for exceeding the 3-hr 162 ppm
H2S limit from the North and South Flare on August 21, 2020. Vale	·
Probable Cause: Flaring was due to an unplanned shutdown of the HCU and subseq	uent startup of the unit.
Corrective actions or <u>Units was normalized and flaring stopped.</u> preventative steps taken:	
Episode ID #:	NOV: <u>60592</u>

B2626 Valero Benicia Refinery							
Facility Address:	Mailing Address:						
3400 East Second Street	3400 East Second Street						
Benicia, CA 945101097	Benicia, CA 945101097						
Contact: Taryn Wier Title: Manager - Environmental Engineering Phone: (707) 745-7475							
Title V deviations for the reporting period are summarized below:							
Event Starte <u>2/23/2023 3:19 PM</u> Stopper <u>2/23/2023</u>	3:19 PM Ongoing Event						
Source Number:	May have resulted in a violation of: Permit:						
Abatement Device: Emission Point: P4-Acid Gas Flare Emission Point, P-4	AQMD: Other: 40 CFR 60.103a(h)						
	023, Valero Benicia Refinery received an NOV (60593) from the BAAQMD. The NOV was issued for						
• •	2/5/2020 from the Acid Gas Flare. Valero submitted a response letter on March 3rd, 2023.						
	nery received an NOV (60593) from the BAAQMD. The NOV was issued for exceeding the 3-hr 162 ppm Flare. Valero will submit a response letter.						
Probable Cause: <u>Flaring from the Acid Gas Flare occurred d</u>	ue to Tail Gas Unit B and subsequent SRU-A trip offline.						
Corrective actions or <u>Operations were normalized and flaring st</u> preventative steps taken:	opped.						
Episode ID #:	NOV: <u>60593</u>						

From 1/1/2023 to 6/30/2023

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Wier T	itle: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start(<u>5/20/2023 1:00 PM</u> Stoppe(<u>5/20/2023 2</u>	2:00 PM Ongoing Event May have resulted in a violation of:
Source Number: S1031-Heat Recovery Steam Generator, SG-4901; Generator, GT-4901	
Abatement Device:	AQMD:
Emission Point: P60-Cogen Stack GT/SG-4901	Other:
1257 Event Description: An upset occurred at GT-4901 (S-1030) resu	lting in the exceedance of the 3-hour CO concentration (at 15% O2) limit at 1 pm on 5/20/2023.
Probable Cause: <u>Compressor (C-4901) tripped and the motor</u>	<u>locked out .</u>
Corrective actions or <u>Compressor was restarted after the thirty m</u> preventative steps taken:	inute lockout and GT-4901 was normalized.

Episode ID #: 08582

NOV:

B2626 Valero Benicia	Refinery						
Facility Address:	Mail	Mailing Address:					
3400 East Second Street	3	400 East S	Second Street				
Benicia, CA 945101097	В	Benicia, CA 945101097					
Contact: Taryn Wier	Title: Manager - Environme	ental Engir	ineering Phone: (707) 745-7475				
Title V deviations for the reporting period ar	summarized below:						
Event Starte	Stoppec5/1/202310:00 AM 🗌 Ongoing Event						
			May have resulted in a violation of:				
Source Number: S1030-Combustion Tur Generator, SG-4901	bine Generator, GT-4901; S1031-Heat Recovery Steam	Permit:					
Abatement Device:		AQMD:	: 1-522.4				
Emission Point:		Other:	:				
recalibrated and	l calibration on 4/30/23 and 5/1/23. Analyzer became ir passed on 5/1/23 @ 10:00 am. The inoperative monitor eyond the following business day after a period of inope	occurrence	ce was discovered on 5/26/23 during a records review and is				
Probable Cause: Calibration drift	and incorrect NOX concentration entered in daily calibra	tion system	<u>m.</u>				
Corrective actions or <u>Re-calibrated an</u> preventative steps taken:	Updated the PLC to read correct calibration value.						
Episode ID #: 08S86		NOV:	': 62190				

From 1/1/2023 to 6/30/2023

B2626 Valero Benicia Refinery	
Facility Address:	Mailing Address:
3400 East Second Street	3400 East Second Street
Benicia, CA 945101097	Benicia, CA 945101097
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start(<u>6/3/2023 12:20 PM</u> Stoppe(<u>6/3/2023</u>	1:05 PM Ongoing Event
Source Number: S1010-Hydrogen Production Facilities	May have resulted in a violation of: Permit: 27609 Part 1
Abatement Device:	AQMD: Reg 8-2-301
Emission Point: P1010-ST-302	Other:
1260 Event Description: <u>On 6/3/23, P017 valve opened from 12:2</u> atmosphere. A project has been underwar Probable Cause: <u>1900# hydrogen grid experienced grid ins</u>	0 pm - 1:05 pm and approximately 119 lbs of total carbon was released from vent P1010 (ST-302) to ay to address releases from this vent during startup, shutdown and process upsets. tability due to change in hydrogen demand by hydrogen consumer.
Corrective actions or <u>Hydrogen Grid pressure was stablilized.</u> preventative steps taken:	

Episode ID #: 08S97

NOV:

B2626 Valero Benicia Refine	ery								
Facility Address:		Mailing Address:							
3400 East Second Street		3400 East Second Street							
Benicia, CA 945101097		Benicia, CA 945101097							
Contact: Taryn Wier	Title: Manager	- Environmental Engineering	Phone: (707) 745-7475						
Certification Statement	Δ.								
I certify under penalty of law that based on the infor reasonable inquiry, the statements and information attachments and other materials are true, accurate,	in this document and in all								
× Johnafilin	Joshua Tulino	Vice President and General M	anager 7/2	20/23					
Signature of Responsible Official	Print Name	Title	Date	/					

	From 1/1/2023 to 6/30/2023
B2626 Valero Beni	cia Refinery
Facility Address: 3400 East Second Street Benicia, CA 945101097	Mailing Address: 3400 East Second Street Benicia, CA 945101097
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Inoperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reporting period are summarized below:	Fuel Opacity/ Wind Guage CEM GLM Gas Parametric NOx SO2 CO H2S TRS NH3 O2 CO2 H2O LTA Lead Steam Flow Dir. Speed pH Temp. VOC Press Image: CEM
Ref: 1249 Event Started: 4/16/2023 7:16 AM Stopped: 4/17/2023 7:16 AM Image: Text Content of the stopped Source Number: S1031-Heat Recovery Steam Generator, SG-4901 Abatement Device: Emission Point:	Event Description: CO failed daily calibration on 4/15/23 and 4/16/23. Analyzer became inoperative for CO on 4/16/23 @7:16 AM. Analyzer was re-calibrated and passed validation on 4/17/23 at 7:16 AM.
Ref: 1255 Event Started: 5/2/2023 3:14 AM Stopped: 5/3/2023 11:48 AM ✓ Has Stopped Source Number: S19-North Flare, ST-2103	Image: Second sec
Abatement Device: Emission Point:	North Flare Total Sulfur failed calibration on 5/1/23 and 5/2/23. Analyzer became inoperative for Total Sulfur on 5/2/23 @3:14 am. Repairs were made to the analyzer and recalibrated and passed on 5/3/22 @11:48 am.
Ref: 1256 Event Started: <u>5/14/2023</u> 7:16 AM Stopped: <u>5/15/2023</u> 2:40 PM Source Number: S1031-Heat Recovery Steam Generator, SG-4901	Image: Second secon
Abatement Device: Emission Point:	validation on 5/15 at 2:40 PM.
Ref: 1258 Event Started: <u>4/30/2023</u> 7:16 AM Stopped: <u>5/1/2023</u> 10:00 AM 🗹 Has Stopped	
Source Number: S1030-Combustion Turbine Generator, GT-4901; S1031-Heat Recovery Steam Generator, SG-4901 Abatement Device: Emission Point:	Event Description: Cogen NOX failed calibration on 4/30/23 and 5/1/23. Analyzer became inoperative for NOX on 4/30/23 at 7:16 am. The analyzer was recalibrated and passed on 5/1/230 @ 10:00 am. The inoperative monitor occurrence was discovered on 5/26/23 during a records review and is being reported beyond the following business day after a period of inoperation greater than 24 continuous hours.

	From 1/1/2023 to 6/30/2023							
B2626 Valero Ben	nicia Refinery							
Facility Address:	Mailing Address:							
3400 East Second Street	-							
Benicia, CA 945101097	Benicia, CA 945101097							
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475							
Inoperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reporting period are summarized below	Fuel Fuel Opacity/ Wind Wind Guage W: CEM GLM Gas Parametric NOx SO2 CO H2S TRS NH3 O2 CO2 H2O LTA Lead Steam Flow Dir. Speed pH Temp. VOC Press.							
Ref: 1259 Event Started: 5/27/2023 10:42 PM Stopped: 5/31/2023 4:49 PM 🗹 Has Stopped								
Source Number: S23-Gas Oil Hydrocracking, F-401	Event Description: F-401 NOX became inoperative for NOX on 5/27/23 @ 10:42 PM. Analyzer repair was completed 5/31/23 at 4:49PM							
Abatement Device:								
Emission Point: P34-F-401 Stack, P-34								
Ref: 1261 Event Started: 6/3/2023 6:30 AM Stopped: 6/6/2023 6:30 AM 🗹 Has Stopped								
Source Number: S1031-Heat Recovery Steam Generator, SG-4901; S1030-Combustion Turbine Generator,	r, Event Description: Cogen SG/GT-4901 became inoperative for H2S, and TRS on 6/3/2023 6:30 AM. Validations were done and passed but printouts misprinted the							
GT-4901	wrong date.							
Abatement Device:								
Emission Point: P60-Cogen Stack GT/SG-4901								
Ref: 1262 Event Started: <u>6/5/2023 11:30 AM</u> Stopped: <u>6/14/2023 9:15 AM</u> 🗹 Has Stopped								
Source Number:	Event Description: Addendum 6/14/23: The RATA was completed 6/14/2023 at 9:15 AM, recertifying the CEMS.							
	The Flexsorb CEMS sample probe has been located in the wrong port. On 6/5/2023, following BAAQMD instruction, the probe was moved to the correct port. The Flexsorb CEMS is pending a recertification by RATA due to the probe relocation that occurred on 6/5/2023 at 11:30 am.							
Abatement Device: A56-Tail Gas Cleanup Unit on SGU A/B Trains (Flexsorb Section)								
Emission Point:								
Ref: 1263 Event Started: 6/19/2023 7:16 AM Stopped: 6/20/2023 3:11 PM 🗹 Has Stopped								
Source Number: S30-Process Furnace, PFR Preheat, F-2901	Event Description: F-2901 became inoperative for NOX and O2 on 6/19/23 at 7:16 AM. A period of greater than 24 hours of inop occurred on 6/20/23 at 7:17 AM. Passing Calibration on 6/20/23 at 15:11 stopped the period of inop.							
Abatement Device:								
Emission Point: P28-SG-2901 Stack, P-28								

From 1/1/2023 to 6/30/2023

Facility Address:		Mailing Address:												
3400 East Second Street	3400 East Second Street			3400 East Second Street				treet						
Benicia, CA 945101097		Benicia, CA 945101097					097							
Contact: Taryn Wier			Title:	Manag	er - Envi	ronmer	ntal Engi	eering	P	one: (707	745-7475			
Contact: Taryn Wier		Fuel	Title:	Manag	er - Envi	ronmer	ntal Engi	eering	P	one: (707 Opacit		Wind	Wind	Gu

I certify under penalty of law that based on the information and belief formed after reasonable inquiry the statements and information in this document and in all attachments and other materials are true, accurate, and complete.

m х Signature of Responsible Official

Joshua Tulino Print Name

Vice President and General Manager Title

7/20/23 Date

			From 1/1/2023 to 6/30/20	023	
A0901	Valero Benicia	Asphalt Plant			
Facility	y Address:		Mail	ling Address:	
300)1 Park Road		3	001 Park Road	
Benicia, CA 94510			B	Benicia, CA 94510	
Contact: Taryn Wier			Title: Manager - Environme	ental Engineering	Phone: (707) 745-7475
Title V deviation	ns for the reporting period a	re summarized below:		_	
Event Starte	4/19/2023 10:30 AM	Stoppec <u>4/19/2023</u>	2:30 PM Ongoing Event		ve resulted in a violation of:
Source Num	nber: S19-Vacuum Heater H	-1 (natural gas, Asphalt P	lant fuel gas)	Permit:	

Abatement Device:		AQMD:	8-18.301
Emission Point:		Other:	
·	ent was found to be leaking >100 ppm total organic compounds d itely blocked in and isolated. On April 20, 2023, Valero Benicia Re	-	• • • • • •

for total organic compound leak greater than 100 ppm from flexible fuel line.

Probable Cause: Normal wear

Corrective actions or	Lines have been replaced on Burner #2 and #4
coventative stens taken.	

preventative steps taken:

Episode ID #:

NOV: 62185

	From 1/1/2023 to 6/30/2023
A0901 Valero Benicia Asphalt Plant	
Facility Address:	Mailing Address:
3001 Park Road	3001 Park Road
Benicia, CA 94510	Benicia, CA 94510
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:	
Event Start: <u>4/19/2023 10:00 AM</u> Stoppe: <u>4/19/2023</u>	2:00 PM Ongoing Event May have resulted in a violation of:
Source Number: S20-Steam Boiler H-2 A (natural gas)	Permit:
Abatement Device:	AQMD: 8-18.309.3
Emission Point:	Other:
•	2A. Vent was leaking greater than 100 PPM during BAAQMD inspection on 4/19/23. On April 20, 2023, 2186) from the BAAQMD. The NOV was issued for total organic compound leak greater than 100 ppm
Probable Cause: <u>Solenoid valve was not in the closed po</u>	sition causing a VOC reading greater than 100 ppm at the vent outlet .
Corrective actions or <u>Solenoid valve was replaced.</u> preventative steps taken:	
Episode ID #:	NOV: <u>62186</u>

From 1/1/2023 to 6/30/2023	
----------------------------	--

A0901 Valero Benicia Asphalt Plant		
Facility Address:	Mail	iling Address:
3001 Park Road	3	3001 Park Road
Benicia, CA 94510	В	Benicia, CA 94510
Contact: Taryn Wier	Title: Manager - Environme	nental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below:		
Event Start: 2/13/2023 12:00 AM Stopper 2/14/2023	1:47 PM 🗌 Ongoing Event	May have resulted in a violation of:
Source Number: S20-Steam Boiler H-2 A (natural gas); S21-Stear	m Boiler H-2 B (natural gas)	Permit: Condition 24198, Part 7
Abatement Device:		AQMD: 9-10-502.1
Emission Point:		Other:
1237 Event Description: <u>Source Test Report for S-20 21 was turne</u> in within 60 days of the source test.	ed in 62 days after the source tes	est was performed. Regulation 9-10-502.1 requires source tests be turned
Probable Cause: Employee missed the due date.		
Corrective actions or <u>Source test was submitted</u> . preventative steps taken:		
Episode ID #:		NOV:

	From 1/1/2023 to 6/30/2023
A0901 Valero Benicia Asphalt Plant	
Facility Address:	Mailing Address:
3001 Park Road	3001 Park Road
Benicia, CA 94510	Benicia, CA 94510
Contact: Taryn Wier	Title: Manager - Environmental Engineering Phone: (707) 745-7475
Title V deviations for the reporting period are summarized below	<i>.</i> .
Event Start:	23 9:33 AM Ongoing Event May have resulted in a violation of:
Source Number: S34-Tank Heater, H-5 (natural gas)	Permit:
Abatement Device:	AQMD: 8-18.309.3
Emission Point:	Other:
-	1605. Vent was leaking greater than 100 PPM during BAAQMD inspection on 4/26/23. On April 27, 2023, / (62187) from the BAAQMD. The NOV was issued for total organic compound leak greater than 100 ppm
Probable Cause: solenoid valve was not in the closed	position causing a VOC reading greater than 100 ppm at the vent outlet .
Corrective actions or <u>Solenoid valve were replaced.</u> preventative steps taken:	
Episode ID #:	NOV: <u>62187</u>

Facility Address:			Mailing Address:			
3001 Park Road		3001 Park Road				
Benicia, CA 94510		Benicia, CA 94510				
Contact: Taryn Wier	Т	itle: Manager -	Environmental Engineering	Phone: (70	7) 745-7475	
/ deviations for the reporting period are .	summarized below:					
fication Statement						
	he information and belief	formed after				
ify under penalty of law that based on t nable inquiry, the statements and infor	mation in this document a					
ify under penalty of law that based on t onable inquiry, the statements and infor	mation in this document a					
tification Statement tify under penalty of law that based on the onable inquiry, the statements and inform chments and other materials are true, ac	mation in this document a		Vice President and General N	Лапаger	7/20/23	
tify under penalty of law that based on t onable inquiry, the statements and infor	mation in this document a curate, and complete.		Vice President and General N Title	Manager	7/20/23 Date	
tify under penalty of law that based on the onable inquiry, the statements and information of the statements and other materials are true, ac	mation in this document a curate, and complete. Joshua Tulino			Лапаger	7/20/23 Date	
ify under penalty of law that based on the statements and information in the statements and information in the statements and other materials are true, ac	mation in this document a curate, and complete. Joshua Tulino			Manager	7/20/23 Date	
ify under penalty of law that based on the nable inquiry, the statements and information information and other materials are true, ac	mation in this document a curate, and complete. Joshua Tulino			Manager	7/20/23 Date	

From 1/1/2023 to 6/30/2023

A0901 Valero Benicia Asphal	t Plant	
Facility Address:	Mailing Address:	
3001 Park Road	3001 Park Road	
Benicia, CA 94510	Benicia, CA 94510	
Contact: Taryn Wier	Title: Manager - Environmental Engineering	Phone: (707) 745-7475

Inoperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reporting period are summarized below

No Inoperable Monitors for this time period.

Certification Statement

I certify under penalty of law that based on the information and belief formed after reasonable inquiry, the statements and information in this document and in all attachments and other materials are true, accurate, and complete.

х

Joshua Tulino

Vice President and General Manager

7/20/23 Date

Signature of Responsible Official

Print Name

Title

Tuesday, July 18, 2023

te



Title V deviations for the reporting period are summarized below:

No deviation for this time period.

Title

Certification Statement

I certify under penalty of law that based on the information and belief formed after reasonable inquiry, the statements and information in this document and in all attachments and other materials are true, accurate, and complete.

х of Responsible Official Signature

Joshua Tulino Print Name Vice President and General Manager

Date

From 1/1/2023 to 6/30/2023

	No. Illing Addresses	
Facility Address:	Mailing Address:	
3400 East Second Street	3400 East Second Stre	et
Benicia, CA 94510	Benicia, CA 94510109	7
Contact: Taryn Wier	Title: Manager - Environmental Engineering	Phone: (707) 745-7475

it

No Inoperable Monitors for this time period.

Certification Statement

I certify under penalty of law that based on the information and belief formed after reasonable inquiry, the statements and information in this document and in all attachments and other materials are true, accurate, and complete.

Joshua Tulino

Vice President and General Manager

7/20/23 Date

Signature of Responsible Official

Print Name

Title

Tuesday, July 18, 2023

х