Title V Semi-Annual Monitoring Verification Report
September 1, 2012 to February 28, 2013

Title V – Monitoring Report Deviations

Source	Permit ID	Description	Deviation Period				Cause of Deviation	Corrective Actions Taken To Remedy or Mitigate Deviation Situation
			Start		End			
			Date	Time	Date	Time		
S-1 Cupola	40 CFR 63.7710(b)(2)	Operating Limit for capture system	09/10/12	Varies	2/28/13	Varies	Numerous issues related to this deviation, from missing gauge hardware, malfunctions, plugging, and incorrect PLC calculations.	Pressure gauge modifications were completed along with plugging issues. PLC calculations to be checked for accuracy.