

ERRATA – AGENDA ITEM #14

Staff propose incorporation of a compliance date for new requirements in the publicly-noticed draft of the rule:

A late comment was submitted to the Air District noting that, without an effective date in Section 8-18-402.1 for new requirements to provide identification codes for connectors, facilities would be immediately out of compliance upon adoption of the proposed amendments. The Air District agrees an effective date is needed in this section. The publicly-noticed language adding connectors to Section 8-18-402.1 is in ~~red strikethrough~~ below. The proposed new language is in blue double underline.

8-18-402 Identification: Any person subject to this Rule shall comply with the following identification requirements:

...

402.1 All valves, ~~connectors~~, pressure relief devices, pumps and compressors, and, effective January 1, 2017, connectors shall be identified with a unique permanent identification code approved by the APCO. This identification code shall be used to refer to the valve, connector, pressure relief device, pump or compressor location. Records for each valve, connector, pressure relief device, pump or compressor shall refer to this identification code.